

RADWG DAY Power Converters Control Part

John Pett

7/12/2001

1 / 16



Rad. Test Team SL/PO/CC

DIGITAL parts and programs • Ch. Martin , Ph. Semanaz, P. Martinod & T. Valzer FALL BACK system & programs • Q. King & P. A. Masson (cooperant) Tunnel NETWORKING & programs ♦ I. Barnett & T. Valzer TRACABILITY system & programs • A. Dinius , N. David & P. Martinod ANALOG ACQUISITION & analysis programs ♦ T. Valzer ANALOG parts

J. Pett & G. Ramseier (Rad.Test Coordinator)





 Introduction Previous test periods Test program 2001 Digital components Analog components Design strategy Combined tests Overall conclusions Tests for 2002



Introduction

- 750 Dipole corrector power converters in the LHC tunnel (mid-arc under the cryostat)
- Both control (DICO) and power part must be radiation tolerant to about 20 Gy. with acceptable reliability
- For the control part a single design using COTS components will be used for all LHC power converters
- Rad tests have been on-going for 3 years



Previous test periods

♦ 1999 - tests of stand-alone WorldFIP

- OK to >300 Gy. This provided the basic communication mechanism to facilitate future testing
- 2000 tests of microcontroller HC16 + EDAC memory via uFIP (stand-alone)
 - OK all memory SEUs 'repaired' but some other areas affected



Test program 2001

Verification of EDAC protected DICO
Tests of a fall-back control interface
Tests of auxiliary digital components
Test of critical analog components
Combined tests with power parts



Digital components

- DICO HC16 + 320C32 (DSP) + memories + uFIP in microcontrolled mode
 - SRAM (256 kBytes), fully protected by EDAC system
 - FLASH (256 kBytes), no errors, no protection
 - ◆ HC16 Internal RAM, errors seen, can not be protected
 - not used
 - HC16 Internal Registers, can not be seen, can not be protected
 - ◆ vital for system integrity, watchdog restart..
 - ◆ 320C32 DSP
- ◆ OK up to 100 Gy.



Digital components

Double uFIP [Fall back solution] As expected, no problems for fast R/W operations ◆ OK up to >>100 Gy. DALLAS / MAXIM [Card identification system] DS2430A (256 bits 1 wire EEPROM) DS18B20 (1 wire digital thermometer) ◆ OK up to >>100 Gy. WorldFIP repeater (RP131 IR178-2CC1) Industrial product, DC-DC converter removed broken after 20 Gy. Needs redesign & retest! URGENT!



- ADC
 - For latch-ups, restart after cutting the power supply and repowering the component

ADS7852BB (12 bits / 4 inputs)

- For QSPI monitoring / diagnostic
- Rapid test : OK up to 40 Gy.
- ADS7807UB (16 bits SAR)
 - ◆ RAD drift @10V is ~ +10 uV/Gy. (see Vref)
 - ◆ OK up to 80 Gy. (1 latch-up)
- LTC1605ACN (16 bits SAR)
 - ◆ RAD drift @10 V is ~ -15 uV/Gy. (see Vref)
 - OK up to 80 Gy. (1 latch-up)



- DAC
 - drift is inside the loop (ADC is used as reference)
 - AD1862N (20 bits audio)
 - RAD drift @ 10 V is ~ -45 uV/Gy.
 - OK up to 80 Gy.
 - MAX542ACPD (16 bits)
 - Some bits are affected, thus the linearity is not acceptable : component rejected.
 - ◆ RAD drift @ 10 V is ~ -70 uV/Gy. (see Vref)
 - AD5542AR (16 bits)
 - ◆ RAD drift is ~ -100 uV/Gy. (see Vref), (1 latch-up)



V reference

TCC2 tunnel temp. stability : ~2 deg.C/month

MAX6325CSA (2,5 V, max. 1ppm/deg.C)

- RAD drift @ 2,5 V is ~ -20 uV/Gy.
- OK up to 80 Gy.

MAX6350CPA (5,0 V,max. 1ppm/deg.C)

- RAD drift @ 10 V is ~ -120 uV/Gy.
- OK up to 10 Gy. (tests not continued)
- LT1236ACS8-10 (10 V typ. 2ppm/deg.C)
 - used as 10 V ref. for calibration purposes
 - RAD drift @ 10 V is ~ -40 uV/Gy.
 - OK up to 80 Gy.



Multiplexer

 MAX337CWI (Dual 8 inputs)

 Regulator

 LM317LZ (used as 5V reg for ADCs & DACs)

 Resistor network (TaN)

 DP1603-1002A (ratio stability vital, used for signal conditioning)

 Operational amplifier

 OPA2227PA

 All the above are OK up to 80 Gy.



Design strategy

RAD Tolerant

- Not all errors can be detected / repaired
 - Minimize by design choices
- Digital (critical) registers
 - rewrite, triple-up: physically and in software
- ◆ Latch-ups
 - Power down, selective restart
- Analog redundancies
 - Hi-reliability PSU, two ADC, swap-over(s)
- Selective restarts, fast reboot, hold DAC value
- More frequent calibrations due to drift



Complete test

(Converter & DICO)

- ◆ 1st try DICO operated up to 9 Gy.
- Ind try DICO operated up to 40 Gy.
- Failure reasons
 - FPGA (DICO) destruction, due to excessive temperature inside power converter case
 - Some material already irradiated (converter)
 - DCCT broken ..open loop operation

Other results in the next presentation



Overall Conclusions

- No major problems for all sensitive parts up to 20 Gy.
- MTBF will not be substantially affected by operating in the tunnel - mid arc
- Over the converter lifetime, a few (<1/year) automatic restarts of the DICO must be expected due to radiation effects and should have minimal impact on operation



Tests for 2002

- Final pre-production DICO version to be assembled and a series of five complete power converters must be fully tested for overall performance and radiation tolerance
- This will enable better statistics for in-service 'restarts' to be estimated
- More 'real-time' monitoring of the radiation level at the exact test location would be most useful